

■ Application

■ General usage example

When high-precision measurement is required, as in a navigation system, use the output of this sensor through an A/D convertor as shown below.

1. Positive voltage (+) and negative voltage (-) are obtained in the clockwise and counter clockwise directions, respectively, with the static output as a reference.
2. It is possible to derive relative angle variation from integrating the output voltage.